

Permit Activity Report: 12/16/2021 to 12/22/2021

Record No: B0595721	Parcel No: 22E06AD00300	Class:	Applied:	10/13/2021
Type: Building/Commercial/New/NA	Fees Req: \$1,192.00	No. Bldgs:	Issued:	12/22/2021
Status Pending	Fees Col: \$1,192.00	No.Units: 1	Val (Value Const.):	\$0.00
OCC:	Balance: \$0.00	Sq. Ft.: 0	Val (Calc):	\$0.00

Address: 13152 SE RUSK RD

Description: Saunders Office - Fire Restoration - Repair fire damage at roof framing, frame garage floor to main floor level, infill garage doors and rebuild back portion of the office

Contact Phone: (503) 657-9800

Applicant: JOHN STEMBER 1419 WASHINGTON ST, SUITE 100 OREGON CITY, OR 97045

Owner: SAUNDERS RONALD & GLENDA 10225 SE 41ST CT MILWAUKIE OR, 97222

Contractor: -

Permit Activity Report: 12/16/2021 to 12/22/2021

Record No: B0595721	Parcel No: 22E06AD00300	Class:	Applied:	10/13/2021
Type: Building/Commercial/New/NA	Fees Req: \$1,192.00	No. Bldgs:	Issued:	12/22/2021
Status: Pending	Fees Col: \$1,192.00	No. Units: 1	Val (Value Const.):	\$0.00
OCC:	Balance: \$0.00	Sq. Ft.: 0	Val (Calc):	\$0.00

Address: 13152 SE RUSK RD

Description: Saunders Office - Fire Restoration - Repair fire damage at roof framing, frame garage floor to main floor level, infill garage doors and rebuild back portion of the office

Contact Phone: (503) 657-9800

Applicant: JOHN STEMBER 1419 WASHINGTON ST, SUITE 100 OREGON CITY, OR 97045

Owner: SAUNDERS RONALD & GLENDA 10225 SE 41ST CT MILWAUKIE OR, 97222

Contractor: -

Totals

Valuation (Cust):	\$0.00
Valuation (Calc):	\$0.00
Square Feet:	0.00
Fees Required:	\$2,384.00
Fees Collected:	\$2,384.00
Balance Due:	\$0.00
APDs Selected:	2